

**Jeff Johnson**  
**Health, Safety & Accident Investigation Services**

advice • knowledge • insight

17 Mill Cottage Park Newtownards Millisle BT22 2FF

Tel: Mobile: +447888843795 - E-Mail - jjeff162@gmail.com

Ing.P.Eur.Jeff Johnson-.IEng.MIET.MBES.CMIOSH.FIIRSM.MSOE.

**Safety Inspection Certificate**

**Ref 2033/21**

**CLIENT/OWNER:** Full Swing entertainment 15 Curryfree Road Waterside Derry Co. Londonderry Bt473uh

**LOCATION OF INSPECTION:** Address Location  
**INDENT No. & DESCRIPTION** Rodeo Bull Multi Ride Model Number – RS2011/99

**GENERIC NAME:** Rodeo Bull Multi Ride S.No: RS2011/067/99

**MANUFACTURER:** Rodeo Sales UK

**YEAR of MANUFACTURE:** 2014

**IMPORTATION DATE:** 2014

**EXAMINATION PROCEDURE:** **Visual Inspection** - have been inspected in accordance - *Declaration of Operational Compliance of an Amusement Device in accordance with Section D of Fairgrounds and Amusement Parks – Guidance on Safe Practice” HSG 175 [Para’s. 122-127]*

Inspection[s] in accordance with HSG 175 Section D Inspecting an amusement device paragraph’s 160-161 – 166 -170 - Visual Inspection as per Section 239 of the Planning and Development Act, 2000 and Regulations made there under:

**RESULTS OF INSPECTION:**

This Safety Certificate is to confirm that on the following date/dates; cited below a thorough examination was carried out on the above named amusement device with due regard to Structural, Electrical and Mechanical Safety.

**It is my opinion that:**

On the final date of inspection the device was in a condition such as not to present a danger to the public and is fit for further use when operated, maintained and controlled in the correct manner and in accordance with the manufacturer’s instructions, where available.

The safety -critical aspects of the device have not deteriorated to an extent which is liable to cause danger;

**It is my opinion that:**

On the final date of inspection all the above mentioned attraction[s] were in a condition such as not to present any danger/risk to the public and are fit for further use when operated, maintained and controlled in the correct manner and in accordance with the manufacturer’s instructions, where available.

<b>Inspection Type:</b>	<b>Name of Inspection Body</b>	<b>Report Ref No: 2033/21</b>
Report of Design Review	N/A	
Report of Conformity	N/A	
Initial Test	Jeff Johnson	2033/21
Mechanical/Structural	Jeff Johnson	2033/21
Functional Test	Jeff Johnson	2033/21
Electrical T.E.R.	Self Certified [Electrical Services]	
N.D.T. Report	N/A	
Visual Inspection	Jeff Johnson	2033/21

**SAFE WORKING LOADS/Speeds - AS PER MANUFACTURING RECOMMENDATIONS:**

Risk Assessment – Operating Manual – Training Instructions [were available and if not to be drawn up]

**Certificate valid for 12 months from 12/08/21 – Expiry Date 12/08/22**

**Ing.P.Eur.Jeff Johnson-.IEng.MIET.MBES.CMIOSH.FIIRSM.MSOE.**

Certificate issued by: Jeff Johnson  
Health-Safety & Accident Investigation Services  
17 Mill Cottage Park  
Millisle  
Newtownards  
BT22 2FF  
Co Down

*Jeff Johnson*